

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

DATAMASTER MAINTENANCE REPORT

RECEIVED 9/14/14-CD

REVIEWED

Co	omplete this report at the time of the regul complete this report whenever the instrumental in the original and send a copy within	ent is service	d or repaired	d and when	ever it is	placed into serv	By Caro	l Day at 12:48 pm, :	Sep 22, 201
1	TAMASTER SN D4150 Inv#127265 NAME OF AGENCY Missouri Sta	оор D		DATE OF INSPECTION 09/07/2014			•		
22	cation of instrument (street and city) 26 Main Street, Forsyth, Missouri 656		TIME OF INSPECTION 9:30 am						
	HECKLIST: Place a mark in the box by ea nere determined.) Unmarked items must					g within establish	ned limits.	. (Write in observ	ed values
Ø	DIAGNOSTIC CHECK (PRINTOUT ATTACHED)			DATE AN	DATE AND TIME (from printout) 09/07/14 - 09:30				
	☑ COMPUTER			☑ DETE	CTOR				
	☑ PROGRAM			☑ FILTE	RS		-		
	HEATERS SAMPLE CHAMBER		<u>49</u> °C	2 QUAR	RTZ STAN	NDARD		P P A MANAGEMENT	Adult
	☐ FLOW DETECTOR			☑ CALIB	RATION				
	PUMP HIGH SPEED			PRINT	ΓER				
Ø	INDICATOR LIGHTS							- Paletonina	
Ø	SIMULATOR SOLUTION SUPPLIER	Guth Laborat	lories, Inc.		LOT # <u>1</u>	3290	_ EXP. D	ATE 10/29/201	5
Ø	SIMULATOR TEMP (34°C ± 0.2°C)	34.0	°C SI	MULATOR S	SN	G6793	_ EXP. D	ATE 01/16/201	5
∇	CALIBRATION CHECK - (ONLY ONE S	STANDARD IS	S TO BE US	SED PER M	AINTEN	ANCE REPORT)	······································	
	Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)								
	0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE 0.080% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE 0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE								
TES	ST 1 • 0.098%	TEST 2 🖛 (0.099%			TEST 3 • 0.0	99%		
V	PERFORM R.F.I. TEST (PRINTOUT AT								
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)									
REF	FUSALS 1 (004) 0	(.0509)	1	(.1014)	1	(.1519)	1	OVER .19	3
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO RESTORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS (USE OTHER SIDE IF NECESSARY).									
This instrument was found to be operating within established guidelines set by the Missouri Department of Health.									
INSPECTING OFFICER SIGNATURE PRINT FULL NAME									
ROTE (FORTE)					Trooper Adam K. Buff				
	II PERMIT NUMBER/EXPIRATION DATE 02/27/2	015			17) 895-				
₹ETU	28	eath Alcohol I 75 James Blv pplar Bluff, MC	/d.	O Departme	nt of Hea	alth and Senior	Services,	Southeast Distri	ct Office



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 13290 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography on October 31, 2013, using a Perkin Elmer Gas Chromatograph Autosystem XL S/N: 610N9030209, and found to contain 0.1202% (w/vol) ethyl alcohol. The expiration date for this lot number is October 29, 2015 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.100 g/210L +/- 3%.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

NIST Traceability:

Testing was conducted using Cerilliant Reference Standard lot number FN122211-02 whose values are traceable to NIST.

All balances are calibrated annually by an outside agency using NIST traceable weights. Calibration verification is done prior to each use utilizing NIST traceable weights.

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

BRC DRIBMENTER NEWLAL NUMBER 204150 MISSOURI STRIE HIGHWAY PATROL 89/87/14 98,39

PINGROWILD CEMON ---

COSTOTION

了我已的我还是一个好本一的对一的的语句之: SEXO

WESTERN CHESTORY THRITHRO

A. O O

3.

FLOW DETECTOR:

929

TICH OPENIE

PERCHOR!

国门门门的第三

STREET NIESTE

25.5

989Y

0X9Y

2629

TRIVIEW THAT

Domestuvakyz(1)+" HICKLMNOPORSTOWSKYZI/J^_.abodefghijklmno ……非典2000/AVA+*+、/0/1000ABO1000***AHVVGCBCBCBEFG

Face This Side Down - This Edge In Fir

Face This Side Down - This Edge

BAC DataMaster Evidence Ticket

BAC DATAMASTER SERIAL NUMBER 204 MISSOURI STATE HIGHWAY PATROL 09/07/14

MISCELLANGOUS DRIA: EXPIRATION DATE: 02/27/15 PERMIT NUMBER: 220034 OFFICER I.B. * ASB TESTING OFFICER: . 10% SOLUTION TESTING 超山下下人民人大

SUPERVISOR MODE ---

TESTING OFFICER:

BURNE THAT EXTERNEL STRNDARD BLUNK TEST EXIMENAL STANDARD INTERMAL STANDARD EXTERNAL STANDARD BLOSK TEST PER THAT (A) (A) (A) (A) * © © . (3) (3) 。 (2000) VERIFIED

∃ 11 H

> **BAC DataMast** Evidence Ticke

SHO DRIBMASTER SERIAL NUMBE MISSOURI STRIE HIGHWRY P \$17.487.68

OFFICER I.U. 450 TRANSPITTE OFFICER: STRIEZB.L.: MOZII-II-III TONIONIO REDU SCHOLLOL REFU! TRANST TIME ROSER 対し下下へのくべ SALLEY PLIES

MINCELLANDOUS DATA: PERMIT NIMBER: 200084 EXPIRATION DATE: 80/07/15 OFFICER I.D.: SAME 公司 MADIO INTERPRESENCE TEST

THE BREATH BYSELVOID

RADIO INTERFERENCE

Operator Signature_

Operator Signature.

Operator Signature.



STATE OF MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES BREATH ALCOHOL PROGRAM



PERMIT TYPE II

ADAM K BUFF

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field service and repairs and operate the following breath analyzer(s): DATAMASTER									
577.020 th	ermination of the alcoholic content of blo rough 577.041, RSMo and 306.111 thre 02/27/2013	ood from a sample of expired air. Permit issued under the provisions of sections ough 306,119 RSMo.							
NUMBER _	230034 02/27/2015	DIRECTOR OF STATE PUBLIC HEALTH LABORATORY 21 Can Director							
		DIRECTOR OF DEPARTMENT OF HEALTH AND SENIOR SERVICES							